

315 BG Low Viscosity Full Synthetic ATF

APPLICATION CHART

BG Low Viscosity Full Synthetic ATF, PN 315, meets or exceeds the performance requirements of the following automatic transmission fluids.

MAKE	ATF PN
Acura	TYPE 3.1 08200-9017A
Aisin Warner	AW-1
Audi	G 052 540, G 055 005, G 055 162, G 060 162
BMW	83 22 0 142 516, 83 22 2 152 426
Chrysler/Mopar	68157995AA, 68157995AB
DSIH	6P805 (GEELY, SSANGYONG, MAHINDRA 6SP)
Ford	MERCON®LV
GM	DEXRON®-VI
Honda	DW-1
Hyundai/Kia	SP-IV, SPH-IV, SP-IV RR, NWS-9638
Jaguar	JDE 26444
JASO	1-A-LV
JWS	3324
Land Rover	JDE 26444
Lexus	WS
Mercedes-Benz	236.12, 236.14, 236.41
Mitsubishi	ATF-J3, ATF-PA, SP-IV
Nissan	MATIC-S
Shell	M-L12108, 3353, M-1375.4, M-1375.6
Toyota	WS (JWS 3324)
Volvo	31256774, 31256675
VW	G 052 540, G 055 005, G 055 162, G 060 162
ZF Friedrichshafen AG	LifeGuard Fluid 6 (S671090255), LifeGuard Fluid 6 Plus (S671090281), LifeGuard Fluid 8 (AA00601304, S671090312)

BG Low Viscosity Full Synthetic ATF is not recommended for use in the following applications:

Ford Type F, Ford MERCON® ULV, XT-12-QULV

Continuously Variable Transmissions (CVTs)

Dual Clutch Transmissions (DCT)

Direct-Shift Gearbox (DSG)

All Mercedes Benz 722.9 transmissions built after June 21, 2010 requiring ATF A0019897803 (236.15)

BG Products, Inc., accepts no liability for excessive use or misuse of this product.

Revision date 9-14-17

Revisions Added to Not Recommended section
- Ford MERCON® ULV, XT-12-QULV

12-9-16 Fixed on Ford:
REMOVED SPACE BETWEEN MERCON® AND LV

10-20-16 Added to Acura:
-TYPE 3.1 08200-9017A

11-2-15 Original